

# FLASH REPORT 3


## August 2018

### Construction Update

Ongoing earthworks in new plant area



Secondary crusher structure being assembled




No of Lost Time Injuries	0
No of Dressing Cases	0
Environmental Incidents	0
No of Mine Employees	34
No of Site Contractors	44
No of Contractors Off-Site	100
As of 22 August 2018	

Secondary screen





**New mining workshop foundation**



**Septic tank completed, area cleared**



**Septic tank cover being cast**



**Inside final product building**



**Main raw water reservoir now complete**



**Servicing of major equipment**



**ROM pad expansion**

